



Columbia County
BUILDING DEPARTMENT
Inspection Affidavit

Permit Number: 32012

I William P. Duffield, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) PS 468 Building Inspector*

License #: CCC1325785 On or about May 8, 2014
 did personally inspect the (Date & time)

- Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
- Roof deck attachment Secondary water barrier Roof to wall connection

work at 2861 SW CR 242, Lake City, FL 32024
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Signature




*OK
 P.C.
 No pictures
 metal
 not
 on
 Purlins*

STATE OF FLORIDA
 COUNTY OF

Sworn to and subscribed before me this 15 day of August, 2014

By William P. Duffield, Notary Public, State of Florida

Deborah D. Yasko
 (Print, type or stamp)



Personally known or
 Produced Identification Type of identification produced.

* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.

