

# Air Conditioner Replacement or Repair Application #76218



Wednesday, May 6, 2026 11:00 AM

## Checklist:

<input type="checkbox"/> Address	<input type="checkbox"/> Application Submitted	
<input type="checkbox"/> Drive/ROW	<input type="checkbox"/> Zoning Review	<input type="checkbox"/> Legal Lot of Record
<input type="checkbox"/> Septic	<input type="checkbox"/> Plans Reviewed	<input type="checkbox"/> Flood Zone
<input type="checkbox"/> Site Use Approved	<input type="checkbox"/> Required Inspections Assigned	<input type="checkbox"/> FDEP Needed
<input type="checkbox"/> Docs Reviewed/Accepted	<input type="checkbox"/> Invoiced	

APPLICANT: Jeremiah Cook PHONE: (386) 752-8558

ADDRESS: 1955 SW Main Blvd Lake City, FL 32025

OWNER: COX STACY A, PHONE: (386) 243-2122

ADDRESS: 153 SW ASHEVILLE WAY LAKE CITY, FL 32024

PARCEL ID: 25-4S-16-03124-103 SUBDIVISION: HICKORY COVE

LOT: 3 BLOCK: PHASE: UNIT: ACRES: 0.31

CONTRACTOR	TYPE	LIC#	BUSINESS NAME
JEREMIAH J COOK	General	CAC1813212	COOK'S HEAT & AIR CONDITIONING INC

### JOB DETAILS

Commercial or Residential Residential

Description of Work HVAC Change-out, Install Rheem 3.5 ton split heat pump.

Unit for? House

Commercial type of Building:

If "Other", please explain

Unit Type Split-System

Work details for job? Replacement Unit-Change Out(Only)

Exterior Equipment Location Ground

Roof top install:

Model RP14AY42AJ2NA

Seer 14.3

Size (Ton): 3

Total Estimated Cost 10344

Matched systems are required. Select one of the following means: AHRI data

### Review Notes: