



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 43146

I Tyler Turner, licensed as a(n) Contractor* /Engineer/Architect,
Print name FS 468 Building Inspector*

License #: CCC1330410 On or about 11/1/21
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 525 NW Brinkley Terr
(Job Site Address)

Based upon that examination I have determined the installation was done according
to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Contractor's Signature

STATE OF FLORIDA
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 3 day of November, 2021

By Tyler Turner, Notary Public, State of Florida



Katelynn Hickman
(Print, type or stamp name)

Personally known X or
Produced Identification _____ Type of identification produced. _____

*** Include photographs of each plane of the roof with the permit
number clearly shown marked on the deck for each inspection.
Place a tape measure next to the nailing pattern to show distance
between nails.**

*** Photographs must clearly show all work and have the permit
number indicated on the roof.**

*** Affidavit and Photographs must be provided when final
inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of
purlins or underlayment, whichever applies.**