Envelope Leakage Test Report (Blower Door Test) Residential Prescriptive, Performance or ERI Method Compliance 2020 Florida Building Code, Energy Conservation, 7th Edition

unsdiction: Columbia Courty	Permit #: 0000 50142
lob Information	
Builder: Builders Community:	Lot: NA
Address: 143 SW Aqua Way	
	e: FL Zip: 32038
	t either the Performance, Prescriptive, or ERI Method
changes per hour at a pressure of 0.2 inch w.g. (50 Pascals) in Cl	
the selected ACH(50) value, as shown on Form R405-2020 (Performance ACH(50) specified on Form R405-2020-Energy Co.	shall be tested and verified as having an air leakage rate of not exceeding ce) or R406-2020 (ERI), section labeled as infiltration, sub-section ACH50. Calc (Performance) or R406-2020 (ERI): 5.000
Testing shall be conducted by either individuals as defined in Section 5 489.105(3)(f), (g), or (i) or an approved third party. A written report of the provided to the code official. Testing shall be performed at any time after the code of the co	ISI/RESNET/ICC 380 and reported at a pressure of 0.2 inch w.g. (50 Pascals). 53.993(5) or (7), Florida Statues.or individuals licensed as set forth in Section ne results of the test shall be signed by the party conducting the test and
measures. 3. Interior doors, if installed at the time of the test, shall be open. 4. Exterior doors for continuous ventilation systems and heat recovery. 5. Heating and cooling systems, if installed at the time of the test, shall 6. Supply and return registers, if installed at the time of the test, shall installed at the time of the test, shall be company. Company Name: I hereby verify that the above Air Leakage results are in accompliant to the compliant of the test. Signature of Tester: Printed Name of Tester: License/Certification #: Soldagas Althorems Soldagas Althorems Althorems License/Certification #:	Phone: 386 - 937 - 233 6 ordance with the 2020 7th Edition Florida Building Code