



**COLUMBIA COUNTY  
BUILDING DEPARTMENT  
Roof Inspection Affidavit**

Permit Number: 41522

I Paul McDaniel, licensed as a(n) Contractor\* /Engineer/Architect,  
Print name FS 468 Building Inspector\*

License #: CCC1330719 On or about 3/19/21  
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal  
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 323 SE Country Club Road Lake City, FL  
(Job Site Address)

Based upon that examination I have determined the installation was done according  
to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

P. McDaniel  
Contractor's Signature

STATE OF FLORIDA  
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 19 day of March, 2021

By Beverly Reed, Notary Public, State of Florida  
Beverly Reed  
(Print, type or stamp name)

Personally known ☒ or  
Produced Identification \_\_\_\_\_ Type of identification produced. \_\_\_\_\_

\* Include photographs of each plane of the roof with the permit  
number clearly shown marked on the deck for each inspection.  
Place a tape measure next to the nailing pattern to show distance  
between nails.

\* Photographs must clearly show all work and have the permit  
number indicated on the roof.

\* Affidavit and Photographs must be provided when final  
inspection is requested.

\* Metal overlay & purlin installations shall have photographs of  
purlins or underlayment, whichever applies.

