



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 000043397

I Daniel Dufresne, licensed as a(n) Contractor* /Engineer/Architect,
Print name FS 468 Building Inspector*

License #: CCC1332763 On or about 12/30/21 @ 2pm,
did personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions

☒ Roof deck attachment ☒ Secondary water barrier ☒ Roof to wall connection

work at 314 SW Dragonfly Ct. Lake City, FL 32024
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)


[Signature]
Contractor's Signature

STATE OF FLORIDA
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 20th day of January, 2022

By Daniel Dufresne, Notary Public, State of Florida

Personally known ☒
Produced Identification ☐



Kyle Woodruff
(Print, Type or stamp name)

* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.