Bensur!





## Columbia County BUILDING DEPARTMENT

## Inspection Affidavit

Permit Number: 31870
I DON RECO
License #, CC 1330 117 On or about JUVE 5 JOTY, did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions  Mailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection work at 1443 NW Fronter Dr LakeCty, FL (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)
Signature 16-12-19
STATE OF FLORIDA COUNTY OF Sworm to and subscribed before me this 3 day of
(Print, type or stamp name)
Personally known or Produced Identification Type of identification produced Identification Notary Public - State of Florida Notary Public - State of Florida Ny Gomm. Expires Jun 16, 2014
* Include photographs of each plane of the roof the perposis market house Noting Asson clearly shown marked on the deck for each inspection. Place the perposition Noting Asson measure next to the nailing pattern to show distance between nails.
* Photographs must clearly show all work and have the permit number indicated on the roof.
* Affidavit and Photographs must be provided when final inspection is requested.

\* Metal overlay & purlin installations shall have photographs of purlins

or underlayment, whichever applies.