



## Columbia County BUILDING DEPARTMENT

Cason

Inspection Affidavit Permit Number: ,licensed as a(n) Contractor\* /Engineer/Architect, FS 468 Building Inspector\* (please print name and circle Lie Type) License #; CCC 1330 117 On or about 224 did personally inspect the (Date & time) Metal attachment per manufacturer's instructions | Nailing of purlin per metal manufacturer's instructions Roof deck attachment Secondary water barrier Roof to wall connection 15791 SWRd 47 FT White FC 32038 Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) Signature STATE OF FLORIDA COUNTY OF Personally known \_\_\_\_\_ or Produced Identification Type of identification produced.

Notary Public - State of Florida

\* Include photographs of each plane of the root populishments [1897].

clearly shown marked on the deck for each inspection.

- measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.