

## Columbia County Howard BUILDING DEPARTMENT Linda

Inspection Affidavit

Permit Number: 31823 ,licensed as a(n) Contractor\* /Engineer/Architect, FS 468 Building Inspector\* (please print name and circle Lie, Type) License #; CCC1330117 On or about  $1May_{1Date & time}$ Metal attachment per manufacturer's instructions Mailing of purlin per metal manufacturer's instructions Roof deck attachment Secondary water barrier Roof to wall connection work at 244 SW Wheat Place Cake City, Fl 32004 Based upon that examination I have determined the installation was done according to the Hurricane Migication Patrof Manual (Based on 553.844 F.S.) Signature STATE OF FLORIDA COUNTY OF
Sworm to and subscribed before me this 5 day of ADVI . 201

By W.S. Police, State of Florida

(Print, type or stamp name) COUNTY OF Personally known Produced Identification Type of identification produced. IVY DENISE MILLIGAN-BOSE \* Include photographs of each plane of the root with phonded Through National Rotary Assn. Clearly shown marked on the deck for each inspection product Through National Rotary Assn. measure next to the nailing pattern to show distance between nails.

- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.