

## COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

remit Number: 000053706
Print name    Contractor* / Engineer/Architect,
License #; CCC1333708 On or about 4/14/2025 11:30Am did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions  Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 3103 SW Sisters Welcome Rd Lake City, FL
Based upon that examination I have determined the installation was done according to the Hyrricarie Mitigation Retrofit Manual (Based on 553.844 F.S.)  Contractor's Signature
STATE OF FLORIDA  COUNTY OF COLUMBIA  Sworn to and subscribed before me this 14th day of APFII . 2025
By Richard Doman Notary Public, State of Florida
ASHLEY BOWEN Commission # HH 387977 Expires May 12, 2027  Commission # HH 387977 (Print, type or stamp name)
roduced Identification Type of identification produced.

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.