

## COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

Permit Number: 000041598
, licensed as a(n) Contractor* /Engineer/Architect,  Print name  FS 468 Building Inspector*
License #; CCC 133 2820 On or about 4-12-21, 400 pm, did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 6839 County Road 242, Lake City, FL 32024 (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurrieane Mitigation Retrofit Manual (Based on 553.844 F.S.)
Contractor's Signature  ANDREW W CARTER Notary Public - State of Florida Commission # GG 985042 My Comm. Expires May 5, 2024 Bonded through National Notary Assn.
COUNTY OF COLUMBIA
Sworn to and subscribed before me this 13 day of April . 20121  By Amberna We Cantag . Notary Public, State of Florida
Andrew W. Carter (Print, type or stamp name)
Personally knownX or Produced Identification Type of identification produced

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.