



**COLUMBIA COUNTY  
BUILDING DEPARTMENT  
Roof Inspection Affidavit**

**Permit Number:** 000042743

I Ben Keeler, licensed as a(n) Contractor\* Engineer/Architect,  
Print name FS 468 Building Inspector\*

License #: CCC1330509 On or about 10/14/2021 12:00 pm,  
did personally inspect the (Date & time)

- ☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions
- ☒ Roof deck attachment ☒ Secondary water barrier ☒ Roof to wall connection

work at 166 Sw Bonifay Glen, Ft. White, FL  
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]  
Contractor's Signature



STATE OF FLORIDA  
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 14<sup>th</sup> day of October, 2021

By Taylor Handy, Notary Public, State of Florida

Taylor Handy  
(Print, type or stamp name)

Personally known X or  
Produced Identification \_\_\_\_\_ Type of identification produced. \_\_\_\_\_

\* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

\* Photographs must clearly show all work and have the permit number indicated on the roof.

\* Affidavit and Photographs must be provided when final inspection is requested.

\* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.