

COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

Permit Number: 42744
Tyler Torner ,licensed as a(n) Contractor* /Engineer/Architect Print name FS 468 Building Inspector*
License #; CCC1330410 On or about 9-16-71 did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 1349 E Duval Sf (Job Site Address)
(Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)
Contractor's Signature
STATE OF FLORIDA COUNTY OF COLUMBIA Sworn to and subscribed before me this 16 day of September . 20121
By Tuler Turner. Notary Public, State of Florida
Notary Public, State of Florida Notary Public State of Florida Katelynn Hickman My Commission HH 143418 Expires 08/17/2025 (Print, type or stamp name)
Personal Marana
Produced Identification Type of identification produced

- * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.