

REMOVE DRYWALL FROM CEILING & REPLACE
REPLACE WATER DAMAGED INSULATION & DRYWALL

A circular green ink stamp from the Columbia County Building Department. The outer ring contains the text "COLUMBIA COUNTY BUILDING DEPARTMENT" at the top and "PLANS EXAMINER" at the bottom. The center of the stamp is divided into three horizontal sections. The top section says "Received for", the middle section says "FILE COPY" in large, bold letters, and the bottom section says "Code Compliance".

WATER DAMAGE TO CEILING
Original -

58

Page: 1