

Faircloth 1133



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 000042311

I Freddie Seyer
Print name

licensed as a(n) Contractor* /Engineer/Architect,
FS 468 Building Inspector*


License #: CCC1332820 On or about 7-28-21 3:00PM
did personally inspect the (Date & time)

- ☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions
☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 515 NW Zack Drive, Lake City, FL 32055
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Contractor's Signature



STATE OF FLORIDA
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 27th day of July, 2021

By Andrew W. Carter, Notary Public, State of Florida

Andrew W. Carter
(Print, type or stamp name)

Personally known ☒ or

Produced Identification _____ Type of identification produced. N/A

* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.