

## COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

Pe	ermit Number: <u>53573</u>
Print name FS 468 E	as a(n) Contractor* /Engineer/Architect, Building Inspector*
License #; <u>CCC133のY/の</u> On or about did personally inspect the	1 3 (7 /27 @ 3pm., (Date & time)
Metal attachment per manufacturer's instructions	Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection	
work at 168 SE Holly Tem	
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)  Contractor's Signature	
STATE OF FLORIDA COUNTY OF COLUMBIA Sworn to and subscribed before me this day o	of March 2022
By Tyler Turner. Notary	Pulation State of Florida  Notary Public State of Florida  Katelynn Hickman  My Commission HH 143418
Personally known or Type of identification produced	

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.