


Columbia County Fire Rescue

Incident Number 23-003854		ncident Date 08/31/2023	NFIRS Number 0003700	Incident Type (111) - Building	fire	
FDID 29091	Station 43			Shift A Shift	District D43	
nitial Dispatch Code FIRE						
larms 1	Working Fire? Yes		was a factor D-19 was not a factor	Critical Incident T	eam	
emporary Resident Inv	volvement					
Hazardous Materials Rel	leased					
Action Taken 1 (11) - Extinguishmen	t by fire service pe	rsonnel				
Action Taken 2 (12) - Salvage & overl	haul					
y AID						
Aid Given/Received (N) - None						
LOCATION						
ocation Type (1) - Street address						
Address 3827 Southwest BIRL	.EY Avenue, LAKE (CITY, Florida, 32024				
Cross Street, USNG, or D	irections			Latitude 0.00000000	Longitude 0.00000000	Census Tract
etector Alerted Occupa	ant					
Property Use (419) - 1 or 2 family (dwelling			Mixed Use		
) TIMES						
PSAP Received 15:10:42, 08/31/2023		Dispatch Notified Time 15:10:42, 08/31/2023	Alarm Ti	me 12, 08/31/2023		
Arrival Time 15:17:14, 08/31/2023		Vater on Fire Time	At Patie	nt Time		

(1) TIMES							
Loss Stop Time	Controlled Time			Last Unit Cleared Time 17:44:08, 08/31/2023			
Total On Scene Time 2 hrs 26 mins 54 sec		Total Incident Time 2 hrs 33 mins 26 sec					
OF COUNTS							
Counts Include Aid Received?							
Suppression:	EMS:		Other:				
Apparatus Personnel 7 10	Apparatus 0	Personnel 0	Apparatus 1	Personnel 1			
\$\$ Loss							
Property:		Content:					
Estimated Property Losses 200000		Estimated Co	ontent Losses		_		
Estimated Property Value 200000		Estimated Co	ontent Value		_		
₽ PERSON/OWNER							
Person:							
Name Coulombe, Rick		Business Nar	me		Phone (386) 292-	3094	
Address 3827 Southwest Birley Avenu	e, Lake city, Florio	da, 32094					
 AUTHORIZATION							
Report Writer:							
Name MCCAULEY, CAMERON	Employee 1209	e Number		Assignment		Authorization Date 08/31/2023	
Officer in Charge:							
Name MCCAULEY, CAMERON	Employee 1209	e Number		Assignment		Authorization Date 08/31/2023	
Quality Control:							
Name	Authoriza	ation Date					

INCIDENT NARRATIVE

Dispatched to a structure fire, upon arrival found a site built home with fire coming out of the roof of the garage, which was attached to the residence. Fire crews entered the garage and the front door to extinguish the fire. Fire was in the attic and spread throughout the entire residence attic. Fire crews were able to extinguish fire in the attic but the entire residence sustained heat, smoke and water damage. Through investigation, there was a propane powered generator outside the residence on the C side. Homeowner stated he was at work, his wife called him and stated that the generator shut off, then called back and stated she heard a "boom and now the garage is on fire". Fire appeared to have started on, near or around the generator and fire extended up the back wall entering the soffit and then the attic space. FI Fire Marshal was called and gave us a phone consult. No other hazards present, all units became available.



Created By: MCCAULEY, CAMERON



	Daar	ding From		Driority
Jse (1) - Suppression	Respond	aing From		Priority Emergent
(1) Supplies.				
Response Delays				
None/No Delay				
Dispatch Time	Enroute	e Time	Arrival Time	
15:11:27, 08/31/2023	15:11:	34, 08/31/2023	15:17:14, 08/31/2023	
At Patient Time	Clear Tii	me	In District Time	
	17:41:	33, 08/31/2023		
ations Takens				
Actions Taken: Provide mannower Pr	ovide apparatus Provid	le equipment, Provide wate	r	
	- 111	1- p		
Person 1: CHASE, JOSI	IUA			
Action Taken 1				
(11) - Extinguishment	by fire service personne	el		
Action Taken 2				
(73) - Provide manpov	ver			
ire Products Exposed To				
•				
•				
Smoke, Heat, Fire	ıt			
Smoke, Heat, Fire	ıt	loves, Structure Firefighting	Helmet, SCBA	
Smoke, Heat, Fire PPE Worn During Incider Coat, Pant, Boots, Ho	ıt	loves, Structure Firefighting Black Soot Around	Helmet, SCBA Black Soot Around	
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction?	nt od, Mask, Firefighting G			
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction?	od, Mask, Firefighting G Barrier Breach	Black Soot Around	Black Soot Around	
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No	od, Mask, Firefighting G Barrier Breach No	Black Soot Around Nose	Black Soot Around Mouth	
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No	od, Mask, Firefighting G Barrier Breach No lures Completed	Black Soot Around Nose No	Black Soot Around Mouth No	
PPE Malfunction? No Decontamination Proces	od, Mask, Firefighting G Barrier Breach No lures Completed	Black Soot Around Nose	Black Soot Around Mouth No	
Smoke, Heat, Fire PPE Worn During Incider Coat, Pant, Boots, Horn PPE Malfunction? No Decontamination Proceed Cleaned neck, face, and	od, Mask, Firefighting G Barrier Breach No lures Completed	Black Soot Around Nose No	Black Soot Around Mouth No	
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No	od, Mask, Firefighting G Barrier Breach No lures Completed	Black Soot Around Nose No	Black Soot Around Mouth No	
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No Pecontamination Proceed Cleaned neck, face, all	od, Mask, Firefighting G Barrier Breach No lures Completed rms, and exposed areas	Black Soot Around Nose No No s, Wet brush gear without so	Black Soot Around Mouth No	
Engine 43 was dispate	Barrier Breach No lures Completed rms, and exposed areas	Black Soot Around Nose No No Wet brush gear without so	Black Soot Around Mouth No Dap	upon arrival we found a single story bric
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No econtamination Proced Cleaned neck, face, and Init Narrative Engine 43 was dispated structure with the gar	Barrier Breach No lures Completed rms, and exposed areas sched to the above locat	Black Soot Around Nose No	Black Soot Around Mouth No Dap In from generator or propane tank. It wented through the roof. engine 43	crew then deployed hose lines to comb
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No econtamination Proced Cleaned neck, face, and Init Narrative Engine 43 was dispated structure with the galland and stop the spread of	Barrier Breach No Jures Completed rms, and exposed areas sched to the above locat rage and half the house of fire the first attempts	Black Soot Around Nose No No Wet brush gear without so ion for a possible explosion well involved and already were unsuccessful until m	Black Soot Around Mouth No Pap In from generator or propane tank. It wented through the roof. engine 43 ore personnel arrived on scene. one	crew then deployed hose lines to comb ce other personnel arrived we were ther
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No econtamination Proced Cleaned neck, face, and Init Narrative Engine 43 was dispate structure with the gate and stop the spread able to extinguish the	Barrier Breach No lures Completed rms, and exposed areas sched to the above locate rage and half the house of fire the first attempts e fire and get to mop up	Black Soot Around Nose No No Wet brush gear without so ion for a possible explosion well involved and already s were unsuccessful until m o mode. after a extensive m	Black Soot Around Mouth No pap In from generator or propane tank. It wented through the roof, engine 43 ore personnel arrived on scene, one one up all hotspots were finally extinop up all hotsp	crew then deployed hose lines to comb ce other personnel arrived we were ther
Smoke, Heat, Fire PE Worn During Incider Coat, Pant, Boots, Hoo PE Malfunction? No Decontamination Proced Cleaned neck, face, and Juit Narrative Engine 43 was dispate structure with the gate and stop the spread able to extinguish the	Barrier Breach No lures Completed rms, and exposed areas sched to the above locate rage and half the house of fire the first attempts e fire and get to mop up	Black Soot Around Nose No No Wet brush gear without so ion for a possible explosion well involved and already were unsuccessful until m	Black Soot Around Mouth No pap In from generator or propane tank. It wented through the roof, engine 43 ore personnel arrived on scene, one one up all hotspots were finally extinop up all hotsp	upon arrival we found a single story bric crew then deployed hose lines to comb ce other personnel arrived we were ther inguished we assisted with cleaning up

Responding From

Use

(1) - Suppression

Response Delays
None/No Delay

Priority Emergent

Г51						
Dispatch Time 15:11:27, 08/31/2023	i	Enroute Time 15:11:42, 08/3	31/2023	Arrival Time 15:23:12, 08/31/2023		
At Patient Time		Clear Time 17:43:05, 08/3	31/2023	In District Time		
Actions Taken: Provide manpower, P	rovide apparati	us, Provide equip	ment, Provide wate	r		
Person 1: HOFFMAN,	JORDON					
Action Taken 1 (11) - Extinguishment	by fire service	personnel				
Action Taken 2 (12) - Salvage & overh	naul					
Fire Products Exposed To Heat, Smoke, Fire, Do						
PPE Worn During Incide Coat, Hood, Pant, Fire		s, Boots, Mask, S	tructure Firefighting	Helmet, SCBA		
PPE Malfunction?	Barrier Brea		lack Soot Around ose	Black Soot Around Mouth		
Decontamination Proce	dures Completed	_				
<u> </u>						
Use (1) - Suppression		Responding Fro	m		Priority Emergent	
Response Delays None/No Delay						
Dispatch Time 15:11:26, 08/31/2023	:	Enroute Time 15:11:36, 08/3	31/2023	Arrival Time 15:23:10, 08/31/2023		
At Patient Time		Clear Time 17:43:09, 08/3	31/2023	In District Time		
Actions Taken: Provide manpower, P	rovide apparati	us, Provide equip	ment, Extinguishmo	ent by fire service personnel		
Person 1: MCCAULEY,	CAMERON					
Person 2: Pitman, Ke						
Action Taken 1						
(11) - Extinguishment	by fire service	personnel				
Action Taken 2 (12) - Salvage & overh	naul					
Action Taken 3 (73) - Provide manpox	wer					

Person 2: Pitman, Kevin Fire Products Exposed To Smoke, Heat, Fire, Debris/Runoff PPE Worn During Incident Coat, Firefighting Gloves, SCBA, Hood, Boots, Mask, Pant, Structure Firefighting Helmet PPE Malfunction? **Barrier Breach Black Soot Around Black Soot Around** Nose Mouth **Decontamination Procedures Completed** T48 **Responding From** Priority (1) - Suppression **Emergent** Response Delays None/No Delay Dispatch Time **Enroute Time** Arrival Time 15:11:25, 08/31/2023 15:11:44, 08/31/2023 15:30:29, 08/31/2023 At Patient Time Clear Time In District Time 17:41:27, 08/31/2023 Actions Taken: Provide manpower, Provide apparatus, Provide equipment Person 1: ERICKSON, JEREMIAH Action Taken 1 (58) - Operate apparatus or vehicle Action Taken 2 (11) - Extinguishment by fire service personnel Action Taken 3 (12) - Salvage & overhaul E48 Use **Responding From** Priority (1) - Suppression **Emergent** Response Delays None/No Delay Dispatch Time **Enroute Time** Arrival Time 15:11:25, 08/31/2023 15:11:39, 08/31/2023 15:24:32, 08/31/2023 At Patient Time Clear Time In District Time 17:41:08, 08/31/2023 Actions Taken: Provide manpower, Provide apparatus, Provide equipment Person 1: THOMAS, JOSHUA Action Taken 1

(58) - Operate apparatus or vehicle

(11) - Extinguishment by fire service personnel Action Taken 3 (12) - Salvage & overhaul Person 2: CANNON, CODY Action Taken 1 (11) - Extinguishment by fire service personnel Action Taken 2 (12) - Salvage & overhaul **BAT48** Use **Responding From** Priority (0) - Other **Emergent** Response Delays None/No Delay Dispatch Time **Enroute Time** Arrival Time 15:11:00, 08/31/2023 15:11:49, 08/31/2023 15:20:18, 08/31/2023 At Patient Time Clear Time In District Time 17:44:08, 08/31/2023 Actions Taken: Provide manpower Person 1: MINTON, MIKE Action Taken 1 (58) - Operate apparatus or vehicle Action Taken 2 (81) - Incident command E44 Use **Responding From** Priority (1) - Suppression **Emergent** Response Delays None/No Delay **Enroute Time** Dispatch Time Arrival Time 15:19:37, 08/31/2023 15:19:37, 08/31/2023 15:30:41, 08/31/2023 At Patient Time Clear Time In District Time 17:38:33, 08/31/2023 Actions Taken: Provide manpower, Provide apparatus, Provide equipment Person 1: ARCHER, MIKEL Action Taken 1 (11) - Extinguishment by fire service personnel Action Taken 2 (12) - Salvage & overhaul

Person 1: ARCHER, N	MIKEL			
Action Taken 3				
(73) - Provide manpo	ower			
Fire Products Exposed				
Smoke, Heat, Fire, D	Debris/Runoff			
PPE Worn During Incide		iloves, Structure Firefighting	; Helmet, SCBA	
PPE Malfunction?	Barrier Breach No	Black Soot Around Nose No	Black Soot Around Mouth No	
Decontamination Proc Wet brush gear with	•	e, arms, and exposed areas		
Person 2: CUTFORD,	CLAY			
Action Taken 1 (11) - Extinguishmer	nt by fire service personn	el		
Action Taken 2 (12) - Salvage & over	rhaul			
Action Taken 3 (73) - Provide manpo	ower			
Action Taken 4 (58) - Operate appar	atus or vehicle			
Fire Products Exposed 7 Smoke, Heat, Fire, D				
PPE Worn During Incide		iloves, Structure Firefighting	; Helmet, SCBA	
PPE Malfunction?	Barrier Breach No	Black Soot Around Nose	Black Soot Around Mouth	
		No	No	
Decontamination Proc Wet brush gear with	•	e, arms, and exposed areas		
Unit Narrative				
garage roof. 44 cre	w assisted 48 crew mem		O side roof , extinguishment, salva	e structure that already vented through the age and overhaul. Engine 44 was released
Created By: ARCHER, MIK	EL			
43				
Use (1) - Suppression	Respor	ding From		Priority Emergent
Response Delays None/No Delay				
Dispatch Time	Enrout	e Time	Arrival Time	

15:17:29, 08/31/2023

15:10:42, 08/31/2023

15:10:42, 08/31/2023

(86) - Investigate Fire Products Exposed To Smoke, Heat, Fire PPE Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PPE Malfunction? Barrier Breach No	43				
Provide manpower, Provide apparatus, Provide equipment, Provide water Person 1: JENKINS, JONATHAN Action Taken 1 (11) - Extinguishment by fire service personnel Action Taken 2 (73) - Provide manpower Lettion Taken 3 (80) - Investigate Per Word burning Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PER Maffunction? Barrier Breach No No No No No No No No No N	At Patient Time			In District Time	
Action Taken 1 (11) - Extinguishment by fire service personnel Action Taken 2 (73) - Provide manpower Action Taken 3 (86) - Investigate Irie Products Exposed To Smoke, Heat, Fire Per Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA Per Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA Per Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA Per Worn During Incident Word No. No. No. No. No. No. No. No. Per Worn During Incident Wet brush gear without soap, Cleaned neck, face, arms, and exposed areas Junit Narrative See engine 43 narrative. Created By JRININS, JONATHUM Fire Module Site INFO Narms Acres Burned Resident Units in Bidg Buildings Involved 1 1 1 4ydrant Identifier Estimated Water Usage 10000 3 (GNITION Acres Origin (75) - Wall surface: exterior Hotal Source (10) - Heat from powered equipment, other Fire Confined to Item Yes Fire Confined to Item Yes		Provide apparatus, Provi	de equipment, Provide water		
(11) - Extinguishment by fire service personnel kidion Taken 2 (73) - Provide manpower kidion Taken 3 (86) - Investigate life Products Exposed To Smoke, Heat, Fire PE Worn During Indedet Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PE Malfunction? No No No No No No No No No N	Person 1: JENKINS, JO	ONATHAN			
Action Taken 2 (73) - Provide manpower Introducts Exposed To Smoke, Heat, Fire PPE Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PPE Malfunction? Barrier Breach No Mose Mose Mouth No	Action Taken 1				
(73) - Provide manpower Action Taken 3 (86) - Investigate Fire Products Exposed To Smoke, Heat, Fire PPEWorn During Indident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PPE Malfunction? No Noe Black Soot Around Mouth No Noe Noe Noe Mouth No Noe Noe Noe Noe Noe Mouth No Noe Noe Noe Noe Noe Noe Noe Noe Noe N	(11) - Extinguishmen	t by fire service personn	el		
(86) - Investigate Fire Products Exposed To Smoke, Heat, Fire PPE Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PPE Malfunction? Barrier Breach No		wer			
Smoke, Heat, Fire PPE Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PPE Malfunction? No Nose Mouth No Nose Mouth Nose Mou	Action Taken 3 (86) - Investigate				
Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA PPE Malfunction? No		Го			
No N			iloves, Structure Firefighting H	Helmet, SCBA	
No N	PPE Malfunction?	Barrier Breach	Black Soot Around	Black Soot Around	
Wet brush gear without soap, Cleaned neck, face, arms, and exposed areas Unit Narrative See engine 43 narrative. Created By: JBNKINS, JONATHAN Fire Module SITE INFO Marms Acres Burned Resident Units in Bldg 1 1 1 Identifier Estimated Water Usage 10000 GOOD Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other tem First Ignited (UU) - Undetermined Fire Confined to Item Yes			Nose	Mouth	
Wet brush gear without soap, Cleaned neck, face, arms, and exposed areas Unit Narrative See engine 43 narrative. Created By: JBNKINS, JONATHAN Fire Module SITE INFO Alarms Acres Burned Resident Units In Bldg 1 1 1 1 IGNITION Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	Dosontomination Bross	aduras Camplatad			
See engine 43 narrative. Created By: JENKINS, JONATHAN Fire Module SITE INFO Alarms Acres Burned Resident Units In Bldg 1 Hydrant Identifier Estimated Water Usage 10000 FIGNITION Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Fire Confined to Item First Ignited (UU) - Undetermined Fire Confined to Item Yes			face, arms, and exposed area	S	
Fire Module SITE INFO Alarms Acres Burned Resident Units In Bldg 1 Hydrant Identifier Estimated Water Usage 10000 IGNITION Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Tire Confined to Iten Yes	Unit Narrative				
Fire Module SITE INFO	See engine 43 narra	ative.			
SITE INFO Alarms					
Acres Burned Resident Units In Bldg Buildings Involved 1 1 Hydrant Identifier Estimated Water Usage 10000 IGNITION Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	Fire Mod	lule			
Hydrant Identifier Estimated Water Usage 10000 IGNITION Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	SITE INFO				
IGNITION Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	Alarms	Acres Burned			
Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	Hydrant Identifier		_		
Area of Origin (76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	GNITION				
(76) - Wall surface: exterior Heat Source (10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes	Area of Origin				
(10) - Heat from powered equipment, other Item First Ignited (UU) - Undetermined Fire Confined to Item Yes		xterior			
(UU) - Undetermined Yes	Heat Source (10) - Heat from pow	vered equipment, other			
Fine of Mahawial Fineh Israinad	Item First Ignited (UU) - Undetermined				Fire Confined to Item? Yes
Ome of waterial erral formed	Type of Material First Ig	nited			

Cause of Ignition					
(3) - Failure of equipm	ent or heat source				
Factors Contributing to I	gnition 1 ire, malfunction, other				
Human Factors Contribu	ting to Ignition				
Est. Age of Person Involve	ed Gender o	f Person Involved			
EQUIPMENT					
Equipment Involved in Ig	gnition				
Equipment Power Source (20) - Gas fuels, other					Equipment Portability (1) - Portable
Brand		Model	Serial Nu	umber	Year
STRUCTURE					
Structure Type (1) - Enclosed building					
Stories Above Grade	Stories Below Grade	Building Status (2) - In normal use			
Length	Width	Total Square Feet 2600 sq ft	Story of Fire Origin		
Fire Spread					
Item Contributing Most	to Flame Spread		Type of Material		
Number of Stories wi	th Damage				
Minor Damage	Significant Damage	Heavy Damage	Extreme Damage	Total Stories	
PROTECTIVE SYST	EMS				
Presence of Detector (1) - Present	Detector (1) - Sm				
Power Supply (4) - Hardwire with battery backup			Detector Operations (2) - Detector operations	ted	
Effectiveness (/Failure Re (1) - Detector alerted	ason) occupants, occupants res	ponded			
Presence of Auto Extingu (N) - None Present	ishing System		System Type		

PROTECTIVE SYSTEMS		
System Operation	# of Sprinklers	Reason for System Failure