

Columbia County BUILDING DEPARTMENT Inspection Affidavit

In UP

Permit Number: 600031164

I Travis Slaughter ,licensed as a	(n) Contractor*/Engineer/Architect,
(please print name and circle Lic. Type)	FS 468 Building Inspector*
License #; C cc 1329097 On or about	7/5/13 12:00 pm.,
Metal attachment per manufacturer's instructions	Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier	Roof to wall connection
work at 567 SN Sanders Way For (Job Site Address)	+ White Fl 32038
Based upon that examination I have determined the instruction Hurricane Mitigation Retrofit Manual (Based on 553.8) Signature	stallation was done according to the 44 F.S.)
STATE OF FLORIDA COUNTY OF	
Sworn to and subscribed before me this 16 day of	JULY . 201 13
By Notary Pu	ıblic, State of Florida
Personally known Produced Identification 1 ype of identification produced. Can (a boo) Personally known 1 ype of identification produced. Can boo 1 ype of identification produced.	
* Include = h = 4 = 1	

- * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.