

Building and Zoning Department

Remodel Application

Invoice

Amount Due

\$166.13

72576

Applicant Information

LESLIE MCDANIEL 2230 SE BAYA DR LAKE CITY FLORIDA 3202

Invoice Date	Permit #
08/11/2025	

Job Location

Parcel: 26-3S-16-02308-118

Owner: GARNER ROBERT M III, GARNER DEBORAH RUTH

Address: 271 NW MALLARD PL

LAKE CITY, FL32055

Contractor Information

LESLIE R MCDANIEL REED MCDANIEL CONSTRUCTION INC 2230 E BAYA DR. STE. 101 LAKE CITY, FL 32055

Contact Us

Phone: (386) 758-1008

Customer Service Hours: Monday-Friday From 8:00 A.M. to 4:30 P.M.

Email:

bldginfo@columbiacountyfla.com

Website:

http://www.columbiacountyfla.com/Bu ildingandZoning.asp

Address:

Building and Zoning Ste. B-21 135 NE Hernando Ave. Lake City, FL 32055

Invoice History

<u>Date</u>	<u>Description</u>	<u>Amount</u>
08/11/2025	Fee: Building Permit Fee Based on Construction Cost	\$137.07
08/11/2025	Fee: Certificate Fee	\$2.00
08/11/2025	Fee: DBPR - Surcharge / Radon	\$2.06
08/11/2025	Fee: Flood Zone Certification Fee	\$25.00
	Amount Due:	\$166.13

Credit card payments can be made online here (fees apply)

Fee balances are not immediately updated using online Credit Card. If you have paid permit fees using the online application site or by another method such as check or cash, please allow time for your payment to be processed.

Inspection Office Hours

Monday - Friday From 8:00 AM to 10:00 AM and

From 1:30 PM to 3:00 PM

Regular Inspection Schedules

All areas North of County Road 242 From 10:00 AM to Noon

All areas South of County Road 242 From 3:00 PM to 5:00 PM

Inspection Requests

Online: (Preferred Method)

Voice Mail: 386-719-2023 or Phone: 386-758-1008

 $\underline{www.columbia county fla.com/InspectionRequest.asp}$

All Driveway Inspections: 386-758-1019 Septic Release Inspections: 386-758-1058

IMPORTANT NOTICE:

Any inspection requested after 4:30 pm, no matter the method, will be received the next business day and will be scheduled by the earliest time slot.

All Inspections require 24 hours notice.

Emergencies will be inspected as soon as possible.