



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 41514

I Robert L. Lenz, licensed as a(n) Contractor* /Engineer/Architect,
Print name FS 468 Building Inspector*

License #: PC29027319 On or about 3-17-21
did personally inspect the (Date & time)

- ☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions
☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 203 SE Montgomery Pl L.C. FL 32024
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Robert L. Lenz
Contractor's Signature

STATE OF FLORIDA
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 15th day of MARCH, 2021

By Laurie Hodson, Notary Public, State of Florida

Personally known ☒ or

Produced Identification ☐ Type of identification produced. _____

(Print, type or stamp name)



* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.