



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 000044087

Daniel Dufresne

Print name

, licensed as a(n) Contractor* /Engineer/Architect,
FS 468 Building Inspector*

License #: CCC1332763
did personally inspect the

On or about 7/22 @ 2pm
(Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal
manufacturer's instructions

☒ Roof deck attachment ☒ Secondary water barrier ☒ Roof to wall connection

work at 415 Hessler Glen Lake City, FL 32024
(Job Site Address)


Based upon that examination I have determined the installation was done according
to the ~~Hurricane Mitigation~~ Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Contractor's Signature

STATE OF FLORIDA
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 28th day of July, 2022

By Daniel Dufresne, Notary Public, State of Florida



Kyla Woodruff
(Print, type or stamp name)

Personally known ☒ or

Produced Identification _____ Type of identification produced. _____

* Include photographs of each plane of the roof with the permit
number clearly shown marked on the deck for each inspection.
Place a tape measure next to the nailing pattern to show distance
between nails.

* Photographs must clearly show all work and have the permit
number indicated on the roof.

* Affidavit and Photographs must be provided when final
inspection is requested.

* Metal overlay & purlin installations shall have photographs of
purlins or underlayment, whichever applies.