

COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

	Permit Number: 000045180
1 <u>Benjamin keeler</u> Print name	licensed as a(n) Contractor /Engineer/Architect, FS 468 Building Inspector*
License #: CC(1330509 did personally inspect the	On or about 9 19 2022 0 12:50, (Date & time)
Metal attachment per manufactu	ner's Instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment M Sec	ondary water barrier Roof to wall connection
1206 C 116	H:010 14911 1/4/1
	e determined the installation was done according
Based upon that examination I have to the Hurricane Mitigation Retrofit M	e determined the installation was done according
Based upon that examination I have to the Hurricane Mitigation Retrofit Management of the Hurricane Mitigation Retrofit Manage	e determined the installation was done according
Based upon that examination I have to the Hurricane Mitigation Retrofit M	determined the installation was done according Manual (Based on 553.844 F.S.)
Based upon that examination I have to the Hurricane Mitigation Retrofit I Contractor's Signature STATE OF FLORIDA COUNTY OF COLUMBIA	this 21 day of Sydember . 2022

- * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.