## Autodesk Build Photo Report - May 23, 2023 LCCF PHASE IV/V reroof in progress inspection request #2

Prepared by : Mike Ervin

May 23, 2023

## Description

Progress photos of Building A Insulation and cap sheet installation . County web site will not let me select in progress inspection requests. My contact information is listed below

Mike Ervin Sr. Superintendent 813-363-0617.



20230523\_090645\_photo **Taken on:** May 23, 2023 9:06 AM 30° 11' 36.33000" N 82° 30' 28.64160" W



20230523\_084719\_photo

**Taken on:** May 23, 2023 8:47 AM 30° 11' 36.57840" N 82° 30' 29.21040" W



20230523\_084651\_photo **Taken on:** May 23, 2023 8:46 AM 30° 11' 35.84040" N 82° 30' 28.14120" W



20230523\_084710\_photo **Taken on:** May 23, 2023 8:47 AM 30° 11' 36.48120" N 82° 30' 28.81080" W



20230522\_114637\_photo **Taken on:** May 22, 2023 11:46 AM 30° 11' 37.25880" N 82° 30' 29.40840" W



20230522\_102604\_photo **Taken on:** May 22, 2023 10:26 AM 30° 11' 36.47040" N 82° 30' 28.29960" W



20230522\_090836\_photo **Taken on:** May 22, 2023 9:08 AM 30° 11' 34.87920" N 82° 30' 28.08000" W



20230522\_090815\_photo

**Taken on:** May 22, 2023 9:08 AM 30° 11' 34.96920" N 82° 30' 27.84960" W



20230522\_090716\_photo

**Taken on:** May 22, 2023 9:07 AM 30° 11' 35.99160" N 82° 30' 28.73160" W




**Taken on:** May 22, 2023 9:07 AM 30° 11' 35.31840" N 82° 30' 28.68120" W



20230519\_091431\_photo **Taken on:** May 19, 2023 9:14 AM 30° 11' 35.58840" N 82° 30' 28.41120" W



20230519\_080216\_photo **Taken on:** May 19, 2023 8:02 AM 30° 11' 36.03120" N 82° 30' 28.59120" W



20230519\_080130\_photo **Taken on:** May 19, 2023 8:01 AM 30° 11' 35.80080" N 82° 30' 28.95840" W



20230519\_080140\_photo **Taken on:** May 19, 2023 8:01 AM 30° 11' 36.48840" N 82° 30' 28.73160" W



20230519\_080123\_photo **Taken on:** May 19, 2023 8:01 AM 30° 11' 35.48040" N 82° 30' 28.96920" W