

Columbia County BUILDING DEPARTMENT Inspection Affidavit



Permit Number: 3/763

Normand-Analysis and Control of the
T Dow Red Jicensed as a(n) Contractor* /Engineer/Architect,
tplease print name and circle Lie. Type) FS 468 Building Inspector*
License #; $CCC1330117$ On or about $+.2914$
did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Mailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 381 SE Andrews Dr Louise City 12 3 30 25
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) Signature Based upon that examination I have determined the installation was done according to the 15 control of
STATE OF FLORIDA COUNTY OF Sworn/to and subscribed before me this day of
By MA HUSE D SOS Wotary Public, State of Florida
Did to 1003C
Personally known or (Print, type or stamp name)
Produced Identification Type of identification produced
* Include photographs of each plane of the root with permits Public 3 and 16, 2014 clearly shown marked on the deck for each inspection Proposition Halonal Rotary Assn. measure next to the nailing pattern to show distance between nails.
* Photographs must clearly show all work and have the permit number indicated on the roof.
* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins

or underlayment, whichever applies.