Columbia County BUILDING DEPARTMENT Inspection Affidavit	
Permit Number: <u>30941</u>	
I <u>GLENN</u> DAVIS, licensed as a(n) Contractor* /Engineer/Arch (please print name and circle Lic Type) FS 468 Building Inspector	
License #; <u>RC0066698</u> On or about <u>4-17-13</u> did personally inspect the (Date & time)	,
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions	
Roof deck attachment Secondary water barrier Roof to wall connection	
work at 2205 S.W. MAYO R.J. LAKE CITY FI. 32055	
(Job Site Address) Based upon that examination I have determined the installation was done according to Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)	0K the 7 e 4-24-13
Signature	
STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this $24$ day of $4pc$ .	<u>13</u>
	BRIAN L. KEPNER COMMISSION # EE 080698 XPIRES. April 4, 2016 Thru Notary Public Underwriters
(Print, type or stamp name)	
Personally known or Produced Identification $X$ Type of identification produced. $O_{C}$ and $A_{C}$	
	•

ŧ

\* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

\* Photographs must clearly show all work and have the permit number indicated on the roof.

\* Affidavit and Photographs must be provided when final inspection is requested.

\* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.