



NFPS



PO BOX 3823
LAKE CITY, FL 32056



PHONE (386) 752-4675
FAX (386) 752-4674



www.nfps.net

2

May 26, 2020

Troy Crews
Building Official
Columbia County
Lake City, FL 32055

REF: MONOLITHIC SLAB/FOUNDATION INSPECTION; SISTERS WELCOME ROAD; JOE PEURRUNG

Mr. Crews:

On December 2, 2019, I visited the site of the above referenced project for the purpose of performing an inspection of the monolithic slab/foundation prior to the placement of the concrete.

I found that the foundation was of the dimensions as specified in the approved construction plans. The reinforcing steel was the proper size and was placed in accordance with the applicable code(s). The slab had an appropriate vapor barrier, properly installed.

Included in this report are photographs documenting my findings.

If you have any questions or need additional information, do not hesitate to contact me

Sincerely,

R. P. (Phil) Bishop, Jr., P.E.
Vice President
P.E. # 38546

xc: Joe Peurrung



THIS DOCUMENT HAS BEEN DIGITALLY SIGNED AND SEALED BY:

Robert P Bishop


ON THE DATE ADJACENT TO THE SEAL

PRINTED COPIES OF THIS DOCUMENT ARE NOT CONSIDERED SIGNED AND SEALED. THE SIGNATURE MUST BE VERIFIED IN THE ELECTRONIC DOCUMENTS.


NORTH FLORIDA PROFESSIONAL SERVICES, INC.
P.O. BOX 3823
LAKE CITY, FL 32056
CERTIFICATE OF AUTHORIZATION: 29011
ROBERT PHILLIP BISHOP, JR., P.E. NO. 38546

Digitally signed by Robert P Bishop
DN: CN=Robert P Bishop,
OU=A01427E00000169E512718A0000276C,
O=NORTH FLORIDA PROFESSIONAL
SERVICES INC., C=US
Date: 2020.05.26 13:40:27-04'00'

THE ABOVE NAMED PROFESSIONAL ENGINEER SHALL BE RESPONSIBLE FOR THE FOLLOWING SHEETS IN ACCORDANCE WITH RULE 61G15-23.004, F.A.C.
Pages 1-4



View of typical corner.



Typical view of the foundation.



Overall view of the slab showing vapor barrier and reinforcement.