Anderson



requested.

or underlayment, whichever applies.

Columbia County BUILDING DEPARTMENT Inspection Affidavit



Permit Number: 318100
 The fivensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lie, Type) FS 468 Building Inspector*
License #; CCC 1330 117 On or about May 13th 2019 did personally inspect the One about May 13th 2019.
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 1869 SW Mayldin Ave Lake City, FL (Job Site Address)
Based upon that examination I have determined the installation was done according to the I-furricane Minimation Potrofit Manual (Based on 553,844 F.S.) 1C.
Signature S-19-19
STATE OF FLORIDA COUNTY OF Sworn/to and subscribed before me this day of May . 201 By HA HUSE M DOJ (Notary Public, State of Florida (Print Hype or stamp name)
(Print, type or stamp name)
Personally known or Produced Identification Type of identification produced. Notary Public - State of Florida Notary Public - S
* Include photographs of each plane of the roof with pointed through Halonal Holary Assn. clearly shown marked on the deck for each inspection phonded through Halonal Holary Assn.
measure next to the nailing pattern to show distance between nails.
* Photographs must clearly show all work and have the permit number indicated on the roof.
* Affidavit and Photographs must be provided when final inspection is

* Metal overlay & purlin installations shall have photographs of purlins