

Personally known ____ or

Produced Identification Type of identification produced

Columbia County **BUILDING DEPARTMENT Inspection Affidavit**

Permit Number: # 3190/ I Robert Feasec, licensed as a(n) Contractor / Engineer/Architect, FS 468 Building Inspector* (please print name and circle Lic Type) License #; $\frac{126/19}{19}$ On or about $\frac{4/26/19}{19}$ On or about $\frac{4}{19}$ (Date & time) Metal attachment per manufacturer's instructions | Nailing of purlin per metal manufacturer's instructions Roof deck attachment Secondary water barrier Roof to wall connection work at 220 SE Deer wood Glen Lake City, for 32025 (Job Site Address) Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this 12 day of _______. 2014 _ . Notary Public, State of Florida (Print, type of stall p nanoon) ISSION # EE 214728
EXPIRES, July 14, 2016
Bonded Thru Notary Public Underwriters

- * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.