386-752-1703 999-999-9999



Summary of Service

Client: 2652524

Keith Smith Construction

Po Box 302

Archer FL 32618-0302 (352) -51-4-2160 **Location:** 136481873

Keith Smith Construction 3642 Sw Herlong St Fort White FL, 32038-5914

Time In: 11-12-2024 15:24:46 **Time Out:** 11-12-2024 16:19:45

Issue: Photo Captured



11-12-2024 16:19:44

With thanks, Robert Olson

In case of poisoning call Poison Control Center @1-800-222-1222

License/Certifications:

Service Technician: Robert Olson

Technician Licences

Order # / Invoice	Status	Service Date	Service Description	Visit Type

70771562 Completed 11-12-2024 PRE CONSTRUCTION SOIL SERVICE MAINTENANCE

TERMITE TREATMENT -

PHASE 1

Recommendations

Area/Device Recommendation Severity Status Date

Device Summary

TypeWith ActivityWithout ActivityUnserviceableTotal InspectedInspection Point0101

Material Application Summary

Material Applied EPA# Dilution (%) Concentrate Quantity UOM Application
Applied Method

Premise Pre-Construction 432-1331 0.1 0.53912 115 GAL Broadcast

(Bayer)

Targeted Pests: Termite, Subterranean Termite

Area/Device of Application:

Equipment Used:

Active Ingredient(s):

SOIL PRETREAT

Power Sprayer

Imidacloprid

Area Treated: 2200 Square Feet


Totals

Material Applied	EPA#	Quantity UOM
Premise Pre-Construction (Bayer)	432-1331	115 GAI

General Comments:

PRODUCT LABELS & SAFETY DATA SHEETS

Product Labels & Safety Data Sheets, please visit: https://lycensed.com/orgs/rentokil/public/chemicals
For NY customers, please select 'NY' as your locale





Detailed Report

Client: 2652524

Keith Smith Construction

Po Box 302

Archer FL 32618-0302 (352) -51-4-2160 **Location:** 136481873

Keith Smith Construction 3642 Sw Herlong St Fort White FL, 32038-5914

Site: Building, Subfloor, Soil pretreat

SOIL PRETREAT No Activity @ 11-12-2024 16:17:46