

COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

Permit Number: 416 39
,licensed as a(n) Contractor* /Engineer/Architect, Print name FS 468 Building Inspector*
License #; CCC 1329482 On or about 1:00 4-13-2021 did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 169 NW Dalton Gin Lake Lity FL 32053
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) Contractor's Signature
STATE OF FLORIDA COUNTY OF COLUMBIA Sworn to and subscribed before me this 3 day of
Produced Identification Type of identification produced

- * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.