Envelope Leakage Test Report (Blower Door Test)

Residential Prescriptive, Performance or ERI Method Compliance 2017 Florida Building Code, Energy Conservation, 6th Edition

Jurisdiction: Columbia Co.	Permit#: 36409
Job Information	\$ 19 0 G u
Builder: AARON SIMPUR Community:	Lot: 47
Address: 614 BEU FLOWER	Unit .
City: LAKE City State:	FZ- Zip:
Air Leakage Test Results Passing results must meet either the Performance, Prescriptive, or ERI Method	
PRESCRIPTIVE METROD. The building or dwelling unit shall be tested and verified as having an air leakage rate of not exceeding 7 air changes per hour at a pressure of 0.2 inch w.g. (50 pascals) in Climate Zones 1 and 2.	
PERFORMANCE of ERI METHOD-The building or dwelling unit shall be tested and verified as having an air leakage rate of not exceeding the Selected ACH(50) value, as shown on PORMIR405-2017 (Performance) or R406-2017 (ERI); section labeled as infiltration, sub-section ACH. ACH(50) Specified on Form R405-2017-Energy Colc (Performance) or R406-2017 (ERI);	
CFM(50) × 60 ÷ /8, /4/2 = 5.8 Building Volume ACH(50) PASS FAIL When ACH(50) is less than 3, Mechanical Ventilation	Method for calculating building volume: Retrieved from architectural plans Code software calculated Field measured and calculated
Testing. Testing shall be conducted in accordance with ANSURESNET/ICC 380 and reported at appressure or 0.2 inche w.g. (50 Pascals). Testing shall be conducted by either individuals as defined in Section, 553.993(5) or (7), Moldor Stowes, or Individuals licensed as set forth in Section 489.105(3)(f), ig., or (i), or an approved that party: A written report of the results of the rest shall be signed by the party conducting the test and provided to the code official. Testing shall be performed at any time after creation of all pentitrations of the building thermal envelope. During testing: 1. Exterior Windows and doors, fireplace and stove doors shall be closed, but not sealed, beyond the intended weatherstripping or other infiltration control measures. 2. Dampers including exhaust, intake, makeup air, back draft and flue dampers shall be closed, but not sealed beyond intended infiltration control measures. 3. Interior doors, if installed at the time of the test, shall be open. 4. Extertor doors for continuous ventilation systems and heat recovery ventilators shall be closed and sealed. 5. Heating and cooling systems, if installed at the time of the test, shall be runned off. 6. Shappy and return registers. If installed at the time of the test, shall be fully open.	
Testing Company	
Company Name: Dustity Justition Phone: 229-561-0/15 I hereby verify that the above Air Leakage results are in accordance with the 2017 6th Edition Florida Building Code Energy Conservation requirements according to the compliance method selected above.	
Signature of Tester: CoRy STALVEY	Date of Test: 4/22/18
Ucense/Certification #: 5061745 Issuing Authority:	
	18.4