

Columbia County BUILDING DEPARTMENT



Inspection Affidavit

Permit Number: 3/056
I faustin Jomes Gallegos ,licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*
License #; 00 /327482 On or about 4 - 25 - 2013
did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 309 NW mallard Pl. 32055 (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)
auto ares dalloes
Signature 7-10-13
STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this 101 day of Tely . 201 3
By Notary Public, State of Florida
Personally known or LAURIE HODSON MY COMMISSION # EE 214728 EXPIRES: July 14, 2016 Bonded Thru Notary Public Underwriters
Produced Identification Type of identification produced.

- * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.