Addendum to permit #24798.

Owner/Contractor - Donald Shea (386) 984 6200

- 1. Addition of pantry door.
- 2. Addition of kitchen window.
- 3. Substitution of 2'x4" stiff legs and concrete screws to support ledgers on both sides of hallway for support of roof trusses and hallway ceiling.
- 4. Substitution of 2"x14" laminated beams for engineered truss on east side of building (similar to the west side).
- 5. Additional 6"x6" columns on east side of building to support the beams discussed in #4.
- 6. Addition of internal footer on the south side of the hallway similar to the footer on the north side.
- 7. Substitution of 2"x6" stud wall on south side of kitchen (wall is not load bearing).
- 8. Addition of 2"x6" stud walls to house plumbing on:
 - a. East wall of kitchen
 - b. East and west walls of laundry
 - c. West wall of pantry

Signed	Date
9	Datc