



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 43114

I Tyler Turner, licensed as a(n) Contractor* /Engineer/Architect,
Print name FS 468 Building Inspector*

License #: CC013704110 On or about 12/13/21,
did personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions

☒ Roof deck attachment ☒ Secondary water barrier ☒ Roof to wall connection

work at 186 SW Dusty Glen
(Job Site Address)


Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Contractor's Signature

STATE OF FLORIDA
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 13 day of December, 2012

By Tyler Turner, Notary Public, State of Florida



Personally known X or
Produced Identification _____ Type of identification produced. _____

*** Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**