

Columbia County BUILDING DEPARTMENT Inspection Affidavit

Permit Number: 0000 3/669 I Barry Joyz ,licensed as a (1) Contractor*/Engineer/Architect, FS 468 Building Inspector* (please print name and circle Lic. Type) License #; <u>CCC'1322953</u> On or about <u>1/6/14</u>
did personally inspect the (Date & time) Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions Roof deck attachment Secondary water barrier Roof to wall connection work at 1709 NW Frontier Dr, Lake City FL 32055 Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) ENTERED STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this 17 day of Jan . 2014 By Geogra. Morsz. Notary Public, State of Florida Personally known or Produced Identification Type of identification produced. * Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.
- * Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.