Roof Replacement or Repair Application #72219

Tuesday, July 22, 2025 1:57 PM



Checklist:				
AddressDrive/ROWSepticSite Use ApprovedDocs Reviewed/Accepte	Zoning Rev Plans Revid Required I		Legal Lot of F Flood Zone nedFDEP Needed	
APPLICANT: Patty Nunley			PHONE: (386) 867	-5960
ADDRESS: 562 NW Orange Street	Lake City, FL 32055			
WNER: LAKE CITY CAPITAL, LLC,			PHONE : (904) 219-5003	
ADDRESS: 1152 SW BUSINESS P	OINT DR LAKE CITY, FL 320)25		
PARCEL ID: 24-4S-16-03102-999	_	SUBDIVISION:		
LOT: BLOCK:	PHASE:		UNIT:	ACRES: 11.11
CONTRACTOR	TYPE	LIC#	BUSINESS NAME	
Barry Joye	General	FL FL	Energy Roofing	
ROOFING JOB DETAILS				
Type Roofing Job			Re	-Cover - New Material over Existing
Further Job Details (Explain if decking	j is being replaced and or Rep	pairs are being done.) Install EPS flute fill attached. I	I. Install EPS fanfold, mechanically Install Duro-Tuff 50 mil pvc system, ttached. Install Duro-Last approved flashings for all penetrations.
Type of structure				Commercial Building
Further Structure Details (if needed)				
Total Estimated Cost				306515
Commercial or Residential				Commercial
Roof Area (for this job) Sq Ft				442
No. of Stories				1
Ventilation:				Off-ridge Vent
Flashing:				Use Existing
Drip Edge:				Replace All
Valley Treatment:				Use Existing
Roof Pitch				Less than 2:12
Second Roof Pitch (if applicable)				
Any cable and/or race-way wiring loca	ated on or within the roof asse	mbly?		No
Is the existing roof being removed?				No
Explain if not removing the existing roofing material?			this is a Retro fit roof. The Duro Tuff 50 mil pvc roof system will go over the top of the existing roof.	
Type of New Roofing Product				Flat or Membrane type
Florida Product Approval Number				FL1559-R19
Product Manufacturer				Duro-Last
Product Description				Duro Tuff PVC system

Other Roofing Product Type Not Listed	
Sealed roof decking options: (Must select an option.)	Other (explain)
Sealed roof decking explanation for other option.	No underlayment. This is a Retro fit roof using a Duro Tuff 50 mil pvc roofing system

Review Notes: