



**COLUMBIA COUNTY  
BUILDING DEPARTMENT  
Roof Inspection Affidavit**

**Permit Number:** 42877

I Roger Whiddon, licensed as a(n) Contractor\* /Engineer/Architect,  
(please print name and circle Lic. Type) FS 468 Building Inspector\*

License #: CCC1330273 On or about 11/5/2021, did  
personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal  
manufacturer's instructions  
☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 177 NW Lake Vista Glen  
(Job Site Address)


Based upon that examination I have determined the installation was done according to the  
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

RW Whiddon  
Signature

STATE OF FLORIDA  
COUNTY OF Columbia

Sworn to and subscribed before me this 5 day of November, 20X 22

By Nancy C. Miller, Notary Public, State of Florida



Personally known ☒ or  
Produced Identification \_\_\_\_\_ Type of identification produced. \_\_\_\_\_

**\* Include photographs of each plane of the roof with the permit  
number clearly shown marked on the deck for each inspection. Place a  
tape measure next to the nailing pattern to show distance between nails.**

**\* Photographs must clearly show all work and have the permit number  
indicated on the roof.**

**\* Affidavit and Photographs must be provided when final inspection is  
requested.**

**\* Metal overlay & purlin installations shall have photographs of purlins  
or underlayment, whichever applies.**