



Columbia County

BUILDING DEPARTMENT

Inspection Affidavit

Permit Number: 31068

I M. Todd, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*

License #: CGC 006209 On or about 5/23/13,
did personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions

☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 337 SE Pearl Terr, Elkhoff
(Job Site Address)

OK
7C
6-5-13

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Signature



STATE OF FLORIDA
COUNTY OF

Sworn to and subscribed before me this 21 day of May, 2013

By [Signature], Notary Public, State of Florida

Personally known ☒ or

Produced Identification Type of identification produced.

(Print, type or stamp name)



*** Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**