

## COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

Permit Number: 00038/76
,licensed as a(n) Contractor* /Engineer/Architect,  Print name  FS 468 Building Inspector*
License #; CCC 1326 197 On or about NOVember 04, 2019 9: 21 AM did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 1453 SW Birley AVF. LANE C'TY FL 32024
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)  Contractor's Signature
STATE OF FLORIDA
Sworn to and subscribed before me this 6 day of NO Utmber . 2019
Sworn to and subscribed before me this day of 201
By Notary Public, State of Florida
BRENDA MEADS Notary Public - State of Florida Commission = GG 090495 My Comm. Expires Jul 30. 2021 Bridded through National Notary Asso.  Personally  Report Notary Asso.  BRENDA MEADS Notary Public - State of Florida Commission = GG 090495 My Comm. Expires Jul 30. 2021 Bridded through National Notary Asso.  (Print, type or stamp name)
Produced Identification Type of identification produced.

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.