



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 000041504

I Tyler Turner, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*

License #: CCC1330410 On or about 03/24/2021, did
personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal
manufacturer's instructions
☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection
work at 400 Southwest Ainsley Glen, Lake City FL 32024
(Job Site Address)

Based upon that examination I have determined the installation was done according to the
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Signature



STATE OF FLORIDA
COUNTY OF

Sworn to and subscribed before me this 30 day of March, 2012 2021

By Deanna P Spicer, Notary Public, State of Florida

Deanna P Spicer
(Print, type or stamp name)

Personally known or
Produced Identification ☒ Type of identification produced. FL License

*** Include photographs of each plane of the roof with the permit
number clearly shown marked on the deck for each inspection. Place a
tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number
indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is
requested.**

*** Metal overlay & purlin installations shall have photographs of purlins
or underlayment, whichever applies.**