

910-6

19-1

NOTES:

- 1) REFER TO HD 91 (RECOMMENDATIONS FOR HANDLING INSTALLATION AND TEMPORARY DRACKING, REFER TO ENGINEER DRAWINGS FOR PERMANENT DRACKING REQUIREMENTS).
- 2) ALL TH05555 (INCLUDING TH05555 UNDER THE BEAM) SHALL BE REMOVED FROM THE SITE EITHER BY REFERRED TO DETAIL X/C OR ALTERNATE DRACKING REQUIREMENTS).
- 3) ALL VALLEYS ARE TO BE CONVENTIONALLY FRAMED BY DULDER.
- 4) ALL TH05555 ARE DESIGNED FOR 2.0c MAXIMUM SPACING, UNLESS OTHERWISE NOTED
- 5) ALL WALLS SHOWN ON PLACEMENT PLAN ARE CONSIDERED TO BE LOAD BEARING, UNLESS OTHERWISE NOTED
- 6) 5X42 TH05555 MUST BE INSTALLED WITH THE TOP BEING UP.
- 7) ALL ROOF TH0555 HANGERS TO BE SIMPSON TH0526 UNLESS OTHERWISE NOTED. ALL FLOOR TH0555 HANGERS TO BE SIMPSON TH0422 UNLESS OTHERWISE NOTED
- 8) BEAM/HEADER/INTEL (HD) TO BE FURNISHED BY DULDER.

THIS LAYOUT IS THE SOLE SOURCE FOR FABRICATION OF TRUSSES AND VOIDS. ALL PREVIOUS ARCHITECTURAL OR OTHER TRUSS LAYOUTS, REVENUE AND APPROVAL OF THIS LAYOUT MUST BE RECEIVED BEFORE ANY TRUSSES WILL BE BUILT. VERIFY ALL CONDITIONS TO INSURE AGAINST CHANGES THAT WILL RESULT IN EXTRA CHARGES TO YOU.

Approved by: \_\_\_\_\_ Date: \_\_\_\_\_



PHONE 904-437-3349 FAX 904-437-3994

PHONE 904-772-6100 FAX 904-772-1973

PHONE 904-755-6894 FAX 904-755-7973

PHONE 407-322-0059 FAX 407-322-5553

**BUILDER  
PRUDENTIAL BUILDERS  
LOT11**

**COLUMBIA, FL**



MODEL	REVISION
-------	----------

**DALTON**

---

**SCALE NTS**

DATE 07/17/07  
CROWN L  
A  
MONDRAGON  
L246428



**TRUSS HANGER INFORMATION**  
Check TRUSS ENGINEERING F for gravity and uplift values if the value exceeds the capacity of a hanger.

(6) HTU26

