

# **Building and Zoning Department**

# Invoice

## Roof Replacement or Repair Application

72638

#### **Applicant Information**

ROBERT FEASEL 537 SW SABRE AVE LAKE CITY, FL32024

### Invoice Date

08/11/2025

# Permit #

**Amount Due** 

\$104.00

## Job Location

Parcel: 08-4S-17-08238-000 Owner: ROGERS JONATHAN, Address: 171 SW BALBOA PL LAKE CITY, FL32025

#### **Contractor Information**

ROBERT A FEASEL ROBBIES ROOFING INC 537 SW SABRE AVE LAKE CITY, FL 32024

#### **Contact Us**

Phone: (386) 758-1008

Customer Service Hours: Monday-Friday From 8:00 A.M. to 4:30 P.M.

Email:

bldginfo@columbiacountyfla.com

Website:

http://www.columbiacountyfla.com/Bu ildingandZoning.asp

Address:

Building and Zoning Ste. B-21 135 NE Hernando Ave. Lake City, FL 32055

## **Invoice History**

<u>Date</u>	<u>Description</u>	<u>Amount</u>
08/11/2025	Fee: Building Permit Fee Based on Construction Cost	\$100.00
08/11/2025	Fee: Certificate Fee	\$2.00
08/11/2025	Fee: DBPR - Surcharge / Radon	\$2.00
	Amount Due:	\$104.00

Credit card payments can be made online here (fees apply)

Fee balances are not immediately updated using online Credit Card. If you have paid permit fees using the online application site or by another method such as check or cash, please allow time for your payment to be processed.

#### **Inspection Office Hours**

Monday - Friday From 8:00 AM to 10:00 AM and

From 1:30 PM to 3:00 PM

#### **Regular Inspection Schedules**

All areas North of County Road 242 From 10:00 AM to Noon

All areas South of County Road 242 From 3:00 PM to 5:00 PM

#### **Inspection Requests**

Online: (Preferred Method) Voice Mail: 386-719-2023 or Phone: 386-758-1008

www.columbiacountyfla.com/InspectionRequest.asp

All Driveway Inspections: 386-758-1019 Septic Release Inspections: 386-758-1058

#### **IMPORTANT NOTICE:**

Any inspection requested after 4:30 pm, no matter the method, will be received the next business day and will be scheduled by the earliest time slot.

## All Inspections require 24 hours notice.

Emergencies will be inspected as soon as possible.