

SCOPE OF WORK – REPAIR

Cheetham, Joyce 219 SE Willow Drive Eastside Village

1. Remove all damaged drywall, insulation and trim. Install and finish to match new drywall, insulation and trim.
2. Remove and replace kitchen cabinets, counter tops and backsplash
3. Replace carpet and pad in dining room
4. Replace light fixtures
5. Prime and paint walls and ceiling of kitchen, dining room and foyer
6. Repair and replace shingles at damaged areas

---

Don Reed  
General Contractor CGC036224  
Don Reed Construction, Inc.

---

Date

