



# Columbia County Fire Rescue

## INCIDENT

Incident Number: 24-006161  
 Incident Date: 12/09/2024  
 NFIRS Number: 0005931  
 Incident Type: (111) - Building fire

FDID: 29091  
 Station: 51  
 Shift: B Shift  
 District: D51

Initial Dispatch Code: STRUCTURE FIRE LVL 3

Alarms: 01  
 Working Fire?: Yes  
 COVID 19 was a factor: No, COVID-19 was not a factor  
 Critical Incident Team: [ ]

Temporary Resident Involvement

Hazardous Materials Released

Action Taken 1: (11) - Extinguishment by fire service personnel

Action Taken 2: (12) - Salvage & overhaul

Action Taken 3: (55) - Establish safe area

*Include Copy  
 w/ packet  
 so fee can  
 be waived.*

## AID

Aid Given/Received: (N) - None

## LOCATION

Location Type: (1) - Street address

Address: 1300 Northwest HUNTSVILLE CHURCH Drive, LAKE CITY, Florida, 32055

Cross Street USNG or Directions	Latitude	Longitude	Census Tract
	0 00000000	0.00000000	

Detector Alerted Occupant

Property Use: (419) - 1 or 2 family dwelling  
 Mixed Use

## TIMES

PSAP Received: 19:06.11, 12/09/2024  
 Dispatch Notified Time: 19:06:11, 12/09/2024  
 Alarm Time: 19:06.11, 12/09/2024