A FDID State State Incident Date	YYYY 2022
	Street or Highway Street Type Suffix FORT WHITE City State Street Type Suffix Street Type Suffix
C Incident Type	E1 Dates and Times Month Day Year Hour Min
F Actions Taken Extinguishment by [11] [fire service personnel] Primary Action Taken (1) [12] [Salvage & overhaul] Additional Action Taken (2) Additional Action Taken (3)	G1 Resources G2 Estimated Dollar Losses and Values LOSSES: Required for all fires if known. None Apparatus Personnel Suppression
	7 Motor oil: from engine or portable container 60 Industrial use ccupants 8 Paint: from paint cans totaling <55 gallons 63 Military use
J Property Use None None	341 ☐ Clinic, clinic-type infirmary 342 ☐ Doctor/Dentist office 361 ☐ Prison or jail, not juvenile 419 ☐ 1- or 2-family dwelling 429 ☐ Multifamily dwelling 439 ☐ Rooming/Boarding house 449 ☐ Commercial hotel or motel 459 ☐ Residential, board and care 459 ☐ Residential, board and care 464 ☐ Dormitory/Barracks 579 ☐ Motor vehicle/boat sales/repairs

K ₁ Person/Entity Invo	lved						
Local Option	300 _ 020 _ 0350						
account option	Business Name (if applicable) Area Code Phone Number						
✓ Check this box if same	MR MARK BRUNER						
address as incident	Mr., Ms., Mrs. First Name MI Last Name Suffix						
location (Section B). Then skip the three	WII., WIS., WIS. 1 IIST NAME WILL LAST NAME SUITA						
duplicate address							
lines.	Number Prefix Street or Highway Street Type Suffix						
П							
9	Post Office Box Apt./Suite/Room City						
	State ZIP Code						
☐ More people invol	ved? Check this box and attach Supplemental Forms (NFIRS-1S) as necessary.						
	s person involved? eck this box and skip						
	of this block. Business Name (if applicable) Area Code Phone Number						
Essai Spilon	Title Sold Trible Names						
Check this box if same							
address as incident	Mr., Ms., Mrs. First Name MI Last Name Suffix						
Then skip the three	III. Editatio						
duplicate address lines.							
	Number Prefix Street or Highway Street Type Suffix						
Π.							
S							
	Post Office Box Apt./Suite/Room City						
	-						
<u>'</u>	State ZIP Code						
Remarks:							
DYLAN DOHRN - T45							
June 9,2022 22:25:50							
TAE arrived of	n scene, assisted with fire suppression and mop up. Once fire was out						
	etting E46 back in service, T45 released by command. T45 assignment						
complete avail							
Complete avai.	labie.						
DYLAN DOHRN -	E45						
June 9,2022 2	1						
E45 arrived on	n scene assisted with fire suppression and mop up, once fire was out						
assisted gett	ing E46 back in service. released by command. E45 assignment complete						
available.							
JAMES THOMAS							
June 10,2022)5:57:36						
n 40 m 40 =	AMMAO						
	ATT48, E-45, T-45, E-44, T-44, E-46, T-46 RESPONDED TO 2457 DAISY RD						
	RE FIRE. E-46 AND T-46 ARRIVED ON SCENE AND ADVISED HOUSE WAS FULLY						
	I 48 ARRIVED ON SCENE AND ASSUMED COMMAND. A WALK AROUND THE HOUSE WAS						
DONE,							
More remarks?	Check this box and attach Supplemental Forms (NFIRS-1S) as necessary.						
	(
M Authorization							
M Authorization							
	CF10 06 10 2022						
Check box if Officer in charge	e ID Signature Position or rank Assignment Month Day Year						
same as Officer in	CF10 06 10 2022						
charge. 🖒 🗸							

Position or rank


Assignment

Signature

Member making report ID

Day

Month



E 3	Supplemental Special Studies Local Option	NFIRS-1S Supplemental
1	Special Study ID# Study Value Study ID# Study Value Study ID#	Special Study Value
5	Special Special Special Special Special Special Special Special Study ID# Study Value Study ID# Study Value Study ID# Study ID# Study ID# Study ID# Study ID#	Special Study Value
L	Remarks: Local Option	75-15 Revision 01/01/04

CF-10 CLOSED A FRONT DOOR TO A HOUSE THAT WAS CLOSE BY SO NO SMOKE WOULD ENTER THE HOUSE. BY THIS TIME ALL CCFR UNITS HAD ARRIVED ON SCENE. E-46 HAD TWO PRECONNECTS PULLED, AND WAS ATTACKING THE FIRE. TWO FF WERE INSIDE WHILE TWO WERE OUTSIDE EXTINGUISHING FIRE. CF-10 SPOKE WITH HOME OWNER AND HE SAID HE WAS SITTING IN A ROOM THEY WERE ADDING ON SMOKING. HE ALSO STATED THAT THERE WAS A CANDLE ON A TABLE NEXT TO HIS CHAIR. HOMEOWNER WENT TO THE OTHER HOUSE TO GET A LOAD OF LAUNDRY AND CAME BACK TO FIRE IN THE ROOM NEXT TO HIS CHAIR.

CF-10 ASKED IF I NEEDED TO CALL FOR RED CROSS, HOME OWNER SAID NO. HOMEOWNER WAS ASKED IF HE HAD INSURANCE AND HE SAID HE WASNT SURE. ALSO VALUE OF STRUCTURE AND CONTENTS STATED IN THIS REPORT ARE ESTIMATES FROM THE HOME OWNER, MR. MARK BRUNER.

FIRE WAS EXTINGUISHED AND MOP UP COMPLETE, ALL CCFR UNITS CLEARED AND RETURNED TO STATIONS. JAT

ALEX ENGLISH - E46 June 10,2022 13:20:29

E46 was dispatched to a structure fire. Upon arrival of engine 46 found the structure was fully involved with flame showing on all four sides. A 1 3/4" attack line was deployed and water was put on the fire. Tanker 46 arrived and a supply line was hooked to engine 46. At this time a 2nd 1 3/4" hand line was deployed. Engine 46 and all other units work their way through the front door of the structure and attack the fire from the inside out. Drywall was pulled and ceiling was pulled up. the fire was extinguished and all hotspots where cooled. After mop up was completed Engine 46 was topped off with water and both hand lines were placed back on the engine. All units went back available and returned quarters.

LARRY SHALLAR III - T48 June 10,2022 19:53:11

T-48 responded to the above location in reference to a mobile home on fire. T-48 arrived on-scene to a working structure fire. 1207 assisted with providing manpower by using 1 3/4 pre-connect hose line with a fog nozzle to extinguish fire from the exterior of the residents. Fire was extinguished. T-48 was released by command after mop-up was complete. No additional hazards were present. T-48 assignment complete and became available.

DYLAN ALVEY - E44 June 12,2022 06:25:45

E44, T44 arrived on scene and E46, T46 were already on scene with a preconnect on the ground. E44 crews made contact with command who stated they were going to use the line on the ground for interior attack. Due to the size of the fire, E44, T44 crews pulled another preconnect and made another interior attack on the back side of the structure. Once fire was out, E44 crews assisted in mop and getting trucks back in service. Once all trucks were placed in order, E44, T44 was released by command. Assignment complete.

Α	FDID AS State A Incident Date A	Station Incident Number
B B ₁	Property Details	Complete if there were any significant amounts of commercial, industrial, energy, or agricultural products or materials on the property, whether or not they became involved. Enter up to three codes. Check one box for each code entered. On-Site Materials Storage Use 1
Вз	Acres burned (outside fires) Less than one acre	On-site material (3) 1
D D1 D2 D3	Type of material first ignited Required only if item first. ignited code is 00 or <70.	Check box if this is an exposure report.
Bra	None If equipment was not involved, skip to Section G. ipment Involved ind	Fa Equipment Power Source Equipment Power Source Fa Equipment Portability 1 Portable 2 Stationary Portable equipment normally can be moved by one or two persons, is designed to be used in multiple locations, and requires no tools to install. Fire Suppression Factors Enter up to three codes. Fire suppression factor (1) Fire suppression factor (2) Fire suppression factor (2) Fire suppression factor (3)
L	Mobile Property Involved None Not involved in ignition, but burned Involved in ignition, but did not burn Involved in ignition and burned Involved in ignition, but did not burned Involved in ignition and burned Involved in ignition	Mobile Property Type and Make Pre-Fire Plan Available

Structure Type If fire was in an enclosed building or a portable/mobile structure, complete the rest of this form. I Enclosed building Portable/Mobile structure Open structure Air-supported structure Thent Open platform (e.g., piers) Underground structure (work areas) Connective structure (e.g., fences) Other type of structure Building Structure I Under cons I Und	Struction se utinely used or renovation secured unsecured olished 3	Total square feet OR
J3 Count the roof as part of Story of fire origin J2 Fire Spread (1 to 24% flam Number of story (1 to 24% flam Number of story (25 to 49% flam Number of story (25 to 49% flam Number of story (25 to 49% flam Number of story (50 to 74% flam Story of fire spread was confined to object of origin, do not check a box (Ref. Block D3, Fire Module). 2 Count the roof as part of the part of story (1 to 24% flam Number of story (50 to 74% flam Story of fire origin (1 to 24% flam Number of story (50 to 74% flam Number of story (50 to 74% flam Story of fire origin (1 to 24% flam Number of story (25 to 49% flam Number of story (35 to 49% flam Numbe	ories w/minor damage tie damage) ories w/significant damage me damage) ories w/heavy damage me damage) ories w/extreme damage	Check if no flame spread OR if same as Material First Ignited (Block D4, Fire Module) OR if unable to determine.
N None Present Skip to Section M 1 Batter 2 Hardw 3 Plug-in 4 Hardw 5 Plug-in 6 Mecha 7 Multip Supplication 1 Smoke 2 Heat 3 Combination smoke and heat 4 Sprinkler, water flow detection 5 More than one type present 0 Other U Undetermined 1 Fire too	prire only normal prire with battery normal prire with battery normal price with battery normal	Alerted occupants, occupants responded Alerted occupants, occupants failed to respond There were no occupants Failed to alert occupants Undetermined Detector Failure Reason Required if detector failed to operate. Power failure, shutoff, or disconnect Improper installation or placement Defective Lack of maintenance, includes not cleaning Battery missing or disconnected Battery discharged or dead Other
M1 Presence of Automatic Extinguishing System N None Present Present Partial System Present Undetermined Type of Automatic Extinguishing System Required if fire was within designed range of AES. Wet-pipe sprinkler Dry-pipe sprinkler Dry chemical system Foam system Halogen-type system Complete rest of Section M Section M Dry elemined Wet-pipe sprinkler Signed range of AES.	M3	to M4) et (go to M4) ate M5 Extinguishing System Failure Required if system failed or not effective. 1 System shut off 2 Not enough agent discharged 3 Agent discharged but did not reach fire 4 Wrong type of system 5 Fire not in area protected

A FDID A State		tion Inciden		2564 0 Expos	<u> </u>		FIRS-10 ersonnel
B Apparatus or Resources	Check if same date as Alarm dithe Basic Module (Block E1).	night is 0000 ate on Hour/Min	Sent X	of ☆	Apparatus Use Check ONE box for eac apparatus to indicate it use at the incident.	ch List up to	ns Taken 4 actions for paratus and sonnel.
	Dispatch 🗹 🔲 📗 📗 Clear 🗹 📗 📗	2202 2221 2346	Sent	<u> </u>	Suppressi EMS Other	on <u>81</u>	. 86
Personnel ☆ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
CF10	JAMES THOMAS		Ø	81	86		
]						
	Dispatch 🗹 🔲 📗 📗 Clear 🗹 📗 📗 📗	2202 2223 2346	Sent		Suppressi EMS Other	on <u> 73</u>	74
Personnel ☆ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1305	LUCAS HARRELL		Ø	73			
1627	ERIC PEACE		Ø	58	73		
	J						
A	ispatch 🗹 🔲 📗 📗 Irrival 🛣 🔲 📗 📗 I	2202 2226 2346	Sent	1	Suppressi EMS Other	on [_73	
Personnel ☆ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1321	DYLAN DOHRN		Ø	58	73		
]]						

NFIRS-10 Revision 01/01/04


A FDID A State	MM DD YYYYY 06 09 2022 L Incident Date Stat	ion Inciden		2564 0 Expos	<u> </u>		IFIRS-10 ersonnel
B Apparatus or Resources	Check if same date as Alarm dathe Basic Module (Block E1).	night is 0000 ate on Hour/Min	Sent X	of ☆	Apparatus Use Check ONE box for eac apparatus to indicate it use at the incident.	ch List up to	ns Taken o 4 actions for paratus and sonnel.
Ar	spatch	2202 2225 2346	Sent	1	☑ Suppressi □ EMS □ Other	on <u>73</u>	
Personnel ★ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1626	BRAD ENGLERT		Ø	58	73		
Ar I 14 i	spatch 🗹 🔝 🔠 ear 🗹 🔛 📗	2202 2215 2346	Sent 🗹	1	Suppressi EMS Other	on <u> 76</u>	
Personnel 🕁	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1609	JULES HECKMAN		Ø	58	76		
Ari	spatch 🗹 🔝 📗 🏻 Irival 🛣 🔛 📗 🗎	2202 2215 2346	Sent	1	Suppressi EMS Other	on <u>11</u>	
Personnel 🕁 ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1320	ALEX ENGLISH		Ø	11	12		

A L FDID State		ion Inciden		2564 0 Expos	<u> </u>		FIRS-10 ersonnel
B Apparatus or Resources	Check if same date as Alarm dathe Basic Module (Block E1).	night is 0000 ate on Hour/Min	Sent X	of ☆	Apparatus Use Check ONE box for eac apparatus to indicate it use at the incident.	ch List up to	ns Taken 4 actions for paratus and sonnel.
A - 111 A	ispatch	2202 2217 2346	Sent	<u> </u>	☑ Suppressi □ EMS □ Other	on [73	74
Personnel 🕁 ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1703	JAMES MOFFITT		Q	58	73	74	
			<u> </u>				
<u> </u>							
A A	ispatch	2202 2217 2346	Sent	1	Suppressi EMS Other	on <u> </u> 76	
Personnel ద ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1314	DYLAN ALVEY		Ø	76			
Ar	spatch 🛛 🔛 📗 📗 📗 ear 🗹 🔛 📗 📗	2202 2226 2346	Sent	_1_	Suppressi EMS Other	on <u> 76</u>	
Personnel ద	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
1207	LARRY SHALLAR III		Ø	76	11	73	

NFIRS-10 Revision 01/01/04

A L FDID State	MM DD YYYYY 06 09 2022 L Incident Date Stat	ion Inciden		2564 0 Expos	<u>. </u>		FIRS-10 ersonnel
B Apparatus or Resources	Check if same date as Alarm dathe Basic Module (Block E1).	night is 0000 ate on Hour/Min	Sent X	of ☆	Apparatus Use Check ONE box for ear apparatus to indicate it use at the incident.	ch List up to	ns Taken 4 actions for laratus and sonnel.
A- I OO I	spatch 🗹 🔲 📗 📗 I	2202 2215 2248	Sent 🗹		Suppressi EMS Other	on [73	
Personnel ☆ ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
5005	JONNY HANDY		Ø	73			
AI	spatch		Sent		Suppressi EMS Other	on	
Personnel 😾	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
Ar	spatch		Sent		Suppressi EMS Other	on	
Personnel ద	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken
II I	I				1		

NFIRS-10 Revision 01/01/04



A		FL 06 09 2022 Station	□ 000256	Delete Change Exposure No Activity Delete Non-NFIRS Fields
	ditional Inci	dent Times Month Day Year Hour Min	N Dispatch Notified	Ionth Day Year Hour Min
	paratus or esources	Dates and Times Midnight is 0000 Month Day Year Hour/Min	5 ID	En Route L
1 ID	POV	En Route 06 09 2022 2208 District 06 09 2022	6 ID	En Route L L L L L L L L L L L L L L L L L L L
2 ID Type		En Route	7 ID	En Route L L L L L L L L L L L L L L L L L L L
3 ID		En Route	8 ID	En Route
4 ID		En Route	9 ID	En Route L