

FIELD DENSITY WORKSHEET

CLIENT Red door Homes DATE 2-2-22
 PROJECT NAME 249 SW Pleasant hill Glen PROJECT NO. (F white)
 EARTH CONTRACTOR 249 SW Pleasant hill Glen PERMIT NO. 21-0984
 COMPACTION REQUIREMENT (%) 95 ☐ Standard Proctor ☒ Modified Proctor TESTED BY LC
 TOTAL ON-SITE TIME _____ FIELD CONTACT _____
 MILES FROM OFFICE _____
☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☒ Building Pad ☐ Building Footing ☐ Other _____

TEST LOCATION	LAB PROCTOR		TEST DEPTH	PROBE DEPTH	% MOIST.	WET DENSITY (PCF)	DRY DENSITY (PCF)	% COMP.
	DENS.	OMC						
App 5' S of N corner	108.8	9.9	F/G	12"	6.5	111.8	104.9	96.5
App center of pad	↓	↓	↓	↓	7.1	113.4	105.9	97.3
App 5' N of S corner	↓	↓	↓	↓	6.3	112.3	105.6	97.1

REMARKS _____

* Density failed to meet minimum project requirement
 ** Retest indicates minimum density requirement was obtained.
 () Client is aware of unsatisfactory test results.