

Work Order

Number	2025-00014675	Request Date	11/19/2025 12:00:00 AM
Type	Water Inspection	Schedule Date	11/19/2025 12:00:00 AM
Priority		Assign Date	
Requester	Amy Fernandez	Assigned To	Scott, William Brian
Account	143360-001	Service Address	623 SW CHESTERFIED CIR
	TRENT GIEBEIG CONSTRUCTION INC Phone:		LAKE CITY, FL 32024

Comments	1113 - Schedule 2-3, Give to Kevin - Verify that they connected to the water meter correctly. Ken can be reached at 386-623-0263 - AF
----------	---

New Meter Device				
		Meter number 100599621		
		MXU number 137215636		

Read	<u>0000010</u>	Read	
			<u>2:30-3:00pm</u>

Read Date	<u>11</u> / <u>19</u> / <u>2025</u>	Read Date	<u> </u> / <u> </u> / <u> </u>
-----------	-------------------------------------	-----------	---

Comments	<u>Meter meter box and Back Flow front left by driveway plumber on site turned on left on</u>
	<u>Meter check valve and Back Flow installed properly</u>

Completed By: _____

Work Order

Number	2025-00014678	Request Date	11/19/2025 12:00:00 AM
Type	Sewer Inspection	Schedule Date	11/19/2025 12:00:00 AM
Priority		Assign Date	
Requester	Amy Fernandez	Assigned To	Scott, William Brian
Account	143360-001	Service Address	623 SW CHESTERFIED CIR
	TRENT GIEBEIG CONSTRUCTION INC Phone:		LAKE CITY, FL 32024

Comments	1113 - Schedule 2-3, Give to Kevin - Verify that they connected to the sewer tap correctly. Ken can be reached at 386-623-0263 - AF
----------	---

New Meter Device				

Read _____

Read _____

_____2:30-3:00pm

Read Date 11 / 19 / 2025

Read Date ____ / ____ / ____

Comments 2 inch grinder pump pipe hooked up properly to our pipe and valve is open
2 inch force, main and valve front left of house by the road

Completed By: Kap