

# Air Conditioner Replacement or Repair Application #76504



Wednesday, May 27, 2026 12:52 PM

## Checklist:

<input type="checkbox"/> Address	<input type="checkbox"/> Application Submitted	
<input type="checkbox"/> Drive/ROW	<input type="checkbox"/> Zoning Review	<input type="checkbox"/> Legal Lot of Record
<input type="checkbox"/> Septic	<input type="checkbox"/> Plans Reviewed	<input type="checkbox"/> Flood Zone
<input type="checkbox"/> Site Use Approved	<input type="checkbox"/> Required Inspections Assigned	<input type="checkbox"/> FDEP Needed
<input type="checkbox"/> Docs Reviewed/Accepted	<input type="checkbox"/> Invoiced	

**APPLICANT:** Janine M. Flegert **PHONE:** (352) 318-5599

**ADDRESS:** 498 SW Ring Court Lake City, FL 32025

**OWNER:** DICKEY DERRICK P, **PHONE:** (239) 672-9551

**ADDRESS:** 1197 NW BROWN RD LAKE CITY, FL 32055

**PARCEL ID:** 28-3S-16-02361-001 **SUBDIVISION:** RANCHETTES UNR

**LOT:** 8 **BLOCK:** B **PHASE:** **UNIT:** **ACRES:** 1.04

CONTRACTOR	TYPE	LIC#	BUSINESS NAME
Ed Miller	General	CAC1813307	Snyder Co.

### JOB DETAILS

Commercial or Residential Residential

Description of Work 3 ton package unit

Unit for? House

Commercial type of Building:

If "Other", please explain

Unit Type Package Unit

Work details for job? Replacement Unit-Change Out(Only)

Exterior Equipment Location Ground

Roof top install:

Model RHPBYB036AJT

Seer

Size (Ton): 3

Total Estimated Cost 12937

Matched systems are required. Select one of the following means: AHRI data

### Review Notes: