



Inspection Report

11/12/2024 3:20:18 PM

Project: Hudson - King Residence

Address: Hudson - Columbia, 386 SW WILDWOOD CT, Permit No. 50630, Lake City, FL

Work Order	BUILDING - RESIDENTIAL 50630	Results	Date	Inspector	License
9001192	Structural Slab Inspection	Pass	09/20/2024	Seth L. Green	BN7696
9001489	Roof and Wall Sheathing Inspection	Pass	10/15/2024	Steven G. Sapp	BN3217
9001837	Framing Inspection	Partial Pass	10/28/2024	Seth L. Green	BN7696
9001838	Window Attachment Inspection	Pass	10/28/2024	Seth L. Green	BN7696
Work Order	ELECTRICAL - RESIDENTIAL 50630	Results	Date	Inspector	License
9001101	Temp Power Pole Inspection	Pass	09/17/2024	Seth L. Green	BN7696
Work Order	PLUMBING - RESIDENTIAL 50630	Results	Date	Inspector	License
9001102	Underground Rough Plumbing Inspection	Pass	09/17/2024	Seth L. Green	BN7696
Work Order	ROOFING - RESIDENTIAL 50630	Results	Date	Inspector	License
9001836	Roof In-Progress Inspection	Pass	10/28/2024	Seth L. Green	BN7696