

Air Conditioner Replacement or Repair Application #75995



Monday, April 20, 2026 6:19 PM

Checklist:

<input type="checkbox"/> Address	<input type="checkbox"/> Application Submitted	
<input type="checkbox"/> Drive/ROW	<input type="checkbox"/> Zoning Review	<input type="checkbox"/> Legal Lot of Record
<input type="checkbox"/> Septic	<input type="checkbox"/> Plans Reviewed	<input type="checkbox"/> Flood Zone
<input type="checkbox"/> Site Use Approved	<input type="checkbox"/> Required Inspections Assigned	<input type="checkbox"/> FDEP Needed
<input type="checkbox"/> Docs Reviewed/Accepted	<input type="checkbox"/> Invoiced	

APPLICANT: Janine M. Flegert **PHONE:** (352) 318-5599

ADDRESS: 498 SW Ring Court Lake City, FL 32025

OWNER: SMITH ANTHONY W, SMITH HOLLY **PHONE:** (813) 244-6525

ADDRESS: 1133 SW MORNING STAR GLN FORT WHITE, FL 32038

PARCEL ID: 35-5S-16-03752-205 **SUBDIVISION:** ANCIENT OAKS

LOT: 5 **BLOCK:** **PHASE:** **UNIT:** **ACRES:** 5.03

CONTRACTOR	TYPE	LIC#	BUSINESS NAME
Miller, Ed	Air Conditioner	CAC1813307	Snyder Co.
Salette, Brian	Electrician	EC13013157	Snyder Co.
Ed Miller	General	CAC1813307	Snyder Co.
Greene, Michael	Plumbing	CFC1434272	Snyder Co.

JOB DETAILS

Unit for? Mobile Home

If "Other", please explain

Unit Type Package Unit

Work details for job? Replacement Unit-Change Out(Only)

Exterior Equipment Location Ground

Roof top install:

Model

Seer

Size (Ton): 3

Total Estimated Cost 12657

Commercial or Residential Residential

Commercial type of Building:

Description of Work 3 ton package unit

Matched systems are required. Select one of the following means: AHRI data

Review Notes: